12-8-04
2005 00 767
6060 SW 135T

NELCO

TESTING AND ENGINEERING SERVICES

FIELD DENSITY TEST REPORT

Batch #
25871

2005 000 767

Client: JP Builders
16216 SW 79 Terrace
Miami, FL 33193

Date: Nov. 24, 2004
Job: D-0411192

Project Name:	Residence
Project Location:	SW 60th Avenue & 13th Street, Miami, Florida

PROCTOR DATA

Proctor No.	Soil Description	Max Dry Density (pcf)	Optimum Moisture (%)
3836	Tan Sand with Some Lime Rock	106.3	10.1
Required Compaction (%)	95	Test Depth Penetration (inches)	12

FIELD DENSITY TEST RESULTS

Test No.	Proct. No.	Test Location	Info No.	Dry Density	% Moist.	% Comp.	Result
1	3836	Lot 2- 6060 SW 12th Street, Miami, Florida- Building Slab	Final	104.1	11.2	97.9	Pass
2	3836	Lot 3- 6061 SW 13th Street, Miami, Florida- Building Slab	Final	103.9	10.6	97.7	Pass
3	3836	Lot 4- 6060 SW 13th Street, Miami, Florida- Building Slab	Final	103.2	11.1	97.0	Pass

Comments: _____

Richard Garcia
Professional Engineer No. 56712
State of Florida

13370 SW 131 Street, Suite 105, Miami, FL 33186 (305) 259-9779